

Operational Issues with Wind Turbine Blades in a Coastal Environment




Marianne Rodgers, Robbie Sanderson, and Heather Norton

Wind Energy Institute of Canada



Wind Energy Institute of Canada

Wind Energy: Power for Canada



- Located in North Cape, Prince Edward Island.
- Independent, not for profit research organization advancing development of wind energy across Canada through research, testing, innovation, and collaboration since 1981
- Team of 12 permanent full-time staff plus students and interns
- Funding from wind park and external contracts

- WEICan's location offers


- 38 acres
- 300° exposure to the Gulf of St. Lawrence
- Strong wind resource (8.9 m/s @80 m) with low turbulence
- Harsh marine, highly corrosive environment
- Icing events during winter months
- Large winter/summer temperature differences



- WEICan's Wind R&D Park includes:

- Five 2 MW DeWind 9.2 Turbines
- 80 m met. Mast
- 109 kW Solar Array
- 223 kWh BESS
- Climate Monitoring Station
- Robust data management system

WEICan Data Topology



AVEVA PI System

- Over 8500 data streams for Wind R&D Park and Site
- Most are 1 Hz data

Visual Systems

- Cameras in Nacelles
- Cameras on Nacelles
- Cameras for PV array

AVEVA

Research at WEICan

Wind Energy: Power for Canada

- Our greatest contribution to renewable energy development is our real-world operational data and expertise
- We have two main research areas
 - Asset Management
 - Grid Integration
- Asset management research focuses on understanding, predicting, and preventing component failures
 - As wind farms age, owners question whether to maintain assets, expand operations, or discontinue investments
 - How do factors such as complex terrain, high capacity factors, icing and severe weather, cold climate, delayed maintenance cycles impact service life and/or performance?
- How can we turn component failures into research opportunities?
 - Generators
 - Bearings
 - Blades

O&M Challenges – Blades major repair



September 2013



October 2013



August 2014

Example of a suction side delamination. The red and green circles mark the same locations on the blades

- April 2013 – Wind farm was commissioned
- Fall 2013 – Blade inspection found cracks in bonding seams, delamination near roots at the suction side. Repairs undertaken.
- Summer 2014 – Further inspections of T1-5 highlighted root core delamination as the biggest issue.
- 2015/16 – Blades were run through a duration and ultimate failure test at a test facility. They identify the same issues with delamination that WEICan experienced.
- 2016 – Consultant hired to develop repair instructions to reinforce the blades. Every blade reinforced under warranty along with a set of spares that WEICan purchased.
- 2016 – WEICan bought 12 more blades. These were not reinforced.

Blade Major Repair Timeline (Post Warranty)

Wind Energy: Power for Canada

- Summer 2020 – Inspection found crack near root at pressure side of 1 blade on T5. Blade was replaced and the rotor was re-balanced.
- Summer 2023 – Began repairs on another set of spare blades.
- October 2024 – Inspection found 4 blades with cracks near the root on the pressure side: 2 were on T4 and 2 on T5. Consultant hired to create reinforcement instructions for the pressure side. They recommended creating 'splints'.
- November 2024 – 3 more blades were given core ramp/shear web retrofits along with “splints”

In summary: 6 reinforced spares (3 with splints) have been used. 9 spares remain.



Service Inspection September 2024

WEICan Blade Summary


Wind Energy: Power for Canada

Turbine	Blade	Blade Commissioned	Low-pressure side repair	High-pressure side repair
1	Blades 1-3	2013	2016	None
2	Blades 1-3	2013	2016	None
3	Blades 1-3	2013	2016	None
4	Blades 1-3	2024	2023-24	None
5	Blade 1	2020	2016	2024
	Blade 2	2024	2016	2024
	Blade 3	2024	2016	2024
4 (ground)	Blades 1-3	2013 (operated for 11 years)	2016	None
5 (ground)	Blades 1-3	2013 (blade 1 operated for 7 years, blades 2 & 3 operated for 11 years)	2016	None

- WEICan is interested in innovative research using both its damaged and operating blades to advance wind energy operations on two subjects:
 - Advance wind energy sustainability concerning blade end of life
 - Presently most end-of-life turbine blades are disposed of in landfills or incinerated – both can have significant negative impacts to the environment
 - Advance blade health monitoring
 - Blade monitoring options are under development and there are no off-the-shelf options

Leading Edge Erosion of Wind Turbine Blades

Wind Energy: Power for Canada



- Wind turbine blades are exposed to precipitation and airborne particles that can erode their surface coating
- Due to the blades' high tip speeds, the portion of the blade furthest from the base usually receives 70% to 80% of the erosion damage
- Untreated, leading edge erosion can reduce energy production, increase maintenance costs and downtime, and, eventually, affect the blades' structural integrity
- Many types of leading edge protection (LEP) materials have been designed to help prevent the erosion of the blade edge

Leading Edge Repair Timeline



- April 2013 – Commissioning (no LEP product, just paint)
- March 2014 - LE paint failure, erosion, pitting, first observed
- November 2014 – Repair work began
- Summer 2015 – Repair work complete
- November 2015 - Paint failure was again observed
- Summer 2016 - The turbine OEM proposed to address the issues through applying leading edge protection (warranty improvements)
 - WEICan begins field study with 4 LEP products







Until this point, work was under warranty with turbine OEM, after this WEICan took on the responsibility

- Summer 2019 – Reapplication of most products
- March 2021 – WEICan represents Canada on IEA Wind Task 46 – Erosion of Wind Turbine Blades
- Summer 2021 – Application of 5th LEP on T1 & T4 – T4 was rejected by manufacturer
- Summer 2022 – Application of 5th LEP on T2, T3 & T5, Reapplication on T4
- January 2023 – Inspections show 5th LEP detached from Blade 1 leading edge and started to bubble on Blade 2 of T1
- September 2023 – 5th LEP repaired on T1
- Winter 2025 – 5th LEP applied to new blades on T5; 6th LEP applied to new blades on T4
- Spring 2025 – bubbles on T3 and T5 LEP; tear on T4 LEP

LEP Failure 2016 and 2019

Wind Energy: Power for Canada

Leading edge damage was observed on most blades: - Pitting - Cracking - Peeling - Bubbling



LEP Failures 2022, 2023, and 2025

Wind Energy: Power for Canada

T4 Tear



T4 Peeling



T5 Air bubbles





Failures observed in each turbine

Wind Energy: Power for Canada

LEP	Type of LEP	Turbine	Date Applied, Damage observed	Types of Damage Observed
1	Paint (2 component epoxy)	T1, T5	2016, 2017, 2019, 2021	Pitting, cracking, peeling, bubbling
2	Paint (polyurethane)	T4	2016, 2017, 2019, 2021	Pitting, peeling
3	Tape (2-component polyurethane)	T2	2016, 2017, 2021	Pitting, peeling, bubbling
4	Tape (2-component polyurethane)	T3	2016, 2019, 2021	Pitting, peeling bubbling
5	Shell (polyurethane)	T1, T2, T3, T4, T5	T1: 2021, 2023 T2: 2022 T3: 2022 T4: 2021, 2022 T5: 2022, 2025	Peeling, bubbling bubbling Peeling, bubbling bubbling
6	Tape (polyurethane)	T4	2025	Tear, peeling

Leading Edge Repair Work Instructions

Wind Energy: Power for Canada

- Each type of protection has specific application instruction. Instructions typically require
 - Filling, sanding, cleaning to achieve a smooth surface
 - Max and min temperatures and relative humidities for curing and drying
- Repairs uptower have wind speed restrictions, depending on method to access the blade



Causes of LEP Failures

Wind Energy: Power for Canada

- LEP providers attribute premature failures to improper/inadequate surface preparation and installation
- Usual causes:
 - Epoxies/adhesives not appropriately activated
 - Surface was not adequately cleaned
 - Blade repairs with fillers or coatings ahead of installation where still curing
 - Conditions may have been appropriate at the start, but were not sustained
 - Skills/experiences of technicians is not adequate
- Original blade manufacturing/blade quality is very important
 - How was it put together, filler, adhesion methods

Summary and Conclusions

Wind Energy: Power for Canada

- WEICan's heavily instrumented turbines and coastal site allow observations that are relevant to offshore wind considerations
- WEICan has had issues with their wind turbine blades since beginning operation
- As a research institute, WEICan turns these operational issues into research opportunities
 - Upon discovering cracks in their blades, WEICan put out a request for expressions of interest in 2025 for:
 - Blade monitoring options
 - Blade end of life options
 - Upon discovering blade leading edge erosion, WEICan carried out a field test for six different leading edge protection materials
 - All types of LEP showed damage in one to two years.
 - WEICan has noted that improper application and blade quality are the most important factors determining the longevity of the LEP materials, rather than the material itself
 - May be not practical to do "proper" application in the field

Questions

Wind Energy: Power for Canada

Contact:

Marianne Rodgers, Scientific Director

marianne.rodgers@weican.ca

WEICan is going to produce 500 GWh this fall!

Follow us to see the countdown!



<https://www.weican.ca/counting-down-to-500gwh/>

Find us on LinkedIn:



<https://ca.linkedin.com/company/weican>

